

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- | | |
|--|---|
| <p>1. Name of the Officer</p> <p>2. Name of the School</p> <p>3. Location with name of Education District/ Sub. District</p> <p>4. Classification of Building as specified in column 4 of the application for fitness certificate and size.</p> <p>5. Period for which the certificate is issued 2023-24</p> <p>6. Nature of defects , if any</p> <p style="margin-left: 20px;">a) Foundation and basement</p> <p style="margin-left: 20px;">b) Superstructure</p> <p style="margin-left: 20px;">c) Doors and Windows</p> <p style="margin-left: 20px;">d) Wood work wrought and put up</p> <p style="margin-left: 20px;">e) Roof</p> <p style="margin-left: 20px;">f) Flooring</p> <p style="margin-left: 20px;">g) Miscellaneous (Cracks, etc.)</p> <p>7. Any major defects noticed which will render the building unsafe in any manner</p> <p>8. Whether maintenance works have been done properly Yes</p> <p>9. Whether the structure is sound or not for conducting classes</p> | <p style="text-align: center;"><u>SNEHA BABU.H</u></p> <p>Bethany Central School, Nangiarkulangara</p> <p style="text-align: center;"><u>Mavelikkara / Alappuzha</u></p> <p>South Block GF including veranda 1x 43.15 x 9.90 x 3.75m</p> <p style="margin-left: 40px;">" FF " 1x 43.15 x 9.90 x 3.75m</p> <p>East Block GF " 1x 43.15 x 9.90 x 3.75m</p> <p style="margin-left: 40px;">porch (South & East) 2x 6.00 x 2.00 x 3.75m</p> <p>East Block FF including veranda 1x 43.15 x 9.90 x 3.75m</p> <p>West Block GF 1x 25.52 x 7.57 x 3.70</p> <p style="margin-left: 40px;">" 1x 2.25 x 2.74 x 3.70</p> <p style="margin-left: 40px;">" 1x 2.98 x 7.57 x 3.70</p> <p style="margin-left: 40px;">Veranda 1x 34.18 x 2.02 x 3.70</p> <p style="margin-left: 40px;">Store 1x 1.98 x 2.88 x 2.50</p> <p style="margin-left: 40px;">FF 1x 6.20 x 7.57 x 3.70</p> <p style="margin-left: 40px;">" 1x 2.25 x 2.74 x 3.70</p> <p style="margin-left: 40px;">Store 1x 1.98 x 2.88 x 2.50</p> <p style="margin-left: 40px;">SF 1x 6.20 x 7.57 x 3.70</p> <p style="margin-left: 40px;">" 1x 2.25 x 2.74 x 3.70</p> <p style="margin-left: 40px;">Store 1x 1.98 x 2.88 x 2.50</p> <p style="margin-left: 40px;">" 1x 2.25 x 2.74 x 3.70</p> <p style="margin-left: 40px;">TF 1x 9.42 x 7.57 x 3.70m</p> <p style="margin-left: 40px;">" 1x 15.86 x 7.57 x 3.70</p> <p style="margin-left: 40px;">Veranda 1x 34.15 x 2.02 x 3.70</p> <p style="margin-left: 40px;">Toilet 1x 2.98 x 7.57 x 3.70</p> <p style="margin-left: 40px;">Store 1x 1.98 x 2.88 x 2.50</p> <p style="margin-left: 40px;">Store Room 1x 4.80 x 2.50</p> <p style="margin-left: 40px;">" 1x 4.80 x 1.98</p> |
|--|---|

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 29/5/23 and found to be fit / ~~unfit~~ to conduct classes, for the period 2023-24 for the reasons stated above.

Place : Cherpad
Date : 29/5/23

Signed

PRINCIPAL
BETHANY CENTRAL SCHOOL
SENIOR SECONDARY
NANGIARKULANGARA-690513
AFFILIATION No: 931027



Sneha Babu

Assistant Engineer
Bethany Central School
Nangiarkulangara
Alappuzha - 690 513
LSGD Section
Cherpad Grama Panchayat