PROVISIONAL FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Assistant Engineer)
(Re: G.O Ms.20/70/PWD Dt. 23-01-1970

1	Name of School	Bethany Central School, Nangiarkulangara
2	Name of Officer	Reshmy
3	Location	Alappuz
4	Period for which the certificate is issued	2025-2
5	Types of Building	Permane

SOUTH BLOCK GF Including Verandah 1x 43.15 9x 3.75 m (4 CR + 1 LAB)

FF Including Verandah 1x 43.15x 9x 3.75 m (6 CR)

WEST BLOCK GF - 1x 25.52 x 7.57 x 3.70 m

1x 2.25 x 2.74 x 3.70 m

1x 2.98 x 7.57 x 3.70 m

verandah - 1x 34.18 x 2.02 x 3 m

Store - 1x 1.98x 2.88 x 2.50 m

FF - 1x 6.20 x 7.57 x 3.70 m (4CR)

1X 2.25 X 2.74 X 3.70 m

Toilet - 1x 2.98x 7.57x 3.70 m

Store - 1x 1.98 x2.88x 2.50 m

SF - 1x 6.20 x 7.57 x 3.70 m (4CR)

1X 2.25 X 2.74 X 3.70 m

Toilet - 1x 2.98x 7.57x 3.70 m

Store - 1x 1.98 x2.88x 2.50 m

Verandah - 1x34.18 x2.02x3.70

1x 2.25x 2.74x 3.40 m

TF - 1X9.42 X 7.57X3.7 m

1x 15.86 x7.57x3.70 m

Verandah - 1x34.18 x2.02x3.70

Toilet - 1x 2.98x 7.57x 3.70 m

Store - 1x 1.98 x2.88x 2.50 m

Stair Room -1x4.80x2.50 m

Over TF - 1X 4.80X1.98 m

EAST BLOCK GF Including Verandah - 1x43.15x 0x3.75 m (3 CR + 3 Others)

FF Including Verandah - 1x 43.15 90 x 3.75 m (6 CR)

Manager
Bethany Central School
Nangiarkulangara
Alappuzha - 690 513

PRINCIPAL
BETHANY CENTRAL SCHOOL
SENIOR SECONDARY
NANGIARKULANGARA-690513
AFFILIATION No. 931027

2x 6.00 x 2.00 x 3.75 m

PORCH (SOUTH&EAST) - 2X 6.00X 2.00 X 3.75 m

TOILET BLOCK - 1X13.60 X7.57 m

1x10.64x5.93 m

6	Nature of defect it any	
	a- Foundation & Basement	
	b-Superstructure	
	c-Doors & Windows	Nil
	d-Wood work wrought and put up	
	e-Roof	
	f-Flooring	
	g-Miscellaneous (Cracks etc.)	Nil
7	Any major defects noticed which will render the building unsafe in any matter	Nil
8	Whether maintenance work have been done properly	Yes
9	Whether the structure is sound or not for conducting classes	The structure is sound for conducting classes under normal weather conditions

Note- 1- The stability of the structure should be examined also with reference to location altitude,intensity of wind, exposure to flood etc.

2- Any additional observation if deemed necessary, the certificate may be furnished separately with the Certificate

Certified that the School was inspected by me on 11/06/2025 and found to be FIT to conduct classes for the period 2025-26 from 11/06/2025 to 10/09/2025

Place - Cheppad

Date - 11/06/2025

Sneha Babu

Assistant Engineer
LSGD Section
Cheppad Grama Panchayat

OFFICE OF THE ASSISTANT ENGINEER LSGD ENGINEERING SECTION CHEPPAD

N.B : All Buildings should be authorised before issuing the next Fitness

Lijiverghese

Manager
Bethany Central School
Nangiarkulangara
Alappuzha - 690 513

Agnet Sr Sec

PRINCIPAL
BETHANY CENTRAL SCHOOL
SENIOR SECONDARY
NANGIARKULANGARA
AFFILIATION